

Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.
Wood Village, OR 97060
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

Vehicle Description

2011 Ford Explorer V6 4D Utility Base 3.5L

VIN	1FMHK7B84BGA40077		
Ext. Color	Silver		
Int. Color	Gray	Interior	Cloth
Mileage	70,483 Actual Miles		
Engine	3.5L 6-Cylinder Gas		
Transmission	Automatic		



Auction Data

Sale Date	To Be Announced		
Run #	To Be Announced	Inv #	3221
Consignor	GSA FLEET SERVICES		

Declarations

Warranty	GSA Regular Terms
Mileage	70,483 Actual Miles
Title	Clear Title
Announcements	2 WHEEL DRIVE

Equipment

- Front Wheel Drive
- Air Conditioning
- Trip Counter
- Steel Wheels
- Hard Top
- Power Brakes
- Automatic Transmission
- Electronic Traction Control
- Dual and Side Air Bags
- Tilt Steering Wheel
- Rear Wiper
- Electric Mirrors
- 6 Cylinder Gas
- Power Windows
- Cruise Control
- AM/FM CD
- Rear Defog
- 7 Passenger
- Power Locks
- Anti Lock Brakes
- Keyless Entry
- Power Steering

Damage Descriptions (CR completed on 4/28/2015 by SKYLAR FICKLIN)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
Front									
1	Front Bumper	Scratched	Multiple Instances						--
2	Hood	Chips	Multiple Instances						--
Front Subtotal				--	--	--	--	--	--
						--	--	--	--

2011 Ford Explorer V6 4D Utility Base 3.5L

VIN: 1FMHK7B84BGA40077

Inv#: 3221

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
---	----------	---------------	----------	----------	----------	--------------	-------------	------------	-------

Interior

3	Carpets	Stained	Multiple Instances						--
4	Headlining	Dirty	Multiple Instances						--
5	Interior	Dirty	Multiple Instances						--
6	Seats	Dirty	Multiple Instances						--
Interior Subtotal				--	--	--	--	--	--

Left

7	Left Front Door	Dents W/ Paint Dmg	Multiple Instances						--
8	Left Qtr Panel	Scratched	Multiple Instances						--
9	Left Rear Door	Scratched	Multiple Instances						--
Left Subtotal				--	--	--	--	--	--

Mechanical

10	Engine	Checked - Ok	None						--
11	Transmission	Checked - Ok	None						--
Mechanical Subtotal				--	--	--	--	--	--

Rear

12	Rear Bumper	Scratched	Multiple Instances						--
Rear Subtotal				--	--	--	--	--	--

Right

13	Right Front Fender	Scratched	Multiple Instances						--
14	Right Qtr Panel	Scratched	Multiple Instances						--

2011 Ford Explorer V6 4D Utility Base 3.5L

VIN: 1FMHK7B84BGA40077

Inv#: 3221

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
15	Right Rear Door	Scratched	> 12 Inches						--



Right Subtotal

--	--	--	--	--	--
--	--	--	--	--	--

Structural

16	Frame	Checked - Ok	None						--
----	-------	--------------	------	--	--	--	--	--	----

Structural Subtotal

--	--	--	--	--	--
--	--	--	--	--	--

Total

--	--	--	--	--	--
--	--	--	--	--	--

Tires

Region	Brand	Size	Tread Depth
Left Front	FIRESTONE	/-	Average (Average)
Left Rear	FIRESTONE	/-	Average (Average)
Right Front	FIRESTONE	/-	Average (Average)
Right Rear	FIRESTONE	/-	Average (Average)
Spare	FACTORY	/-	Average (Average)

Miscellaneous

Coolant level	OK
Interior odor	OK
Oil level	OK
Transmission fluid level	OK

Images



2011 Ford Explorer V6 4D Utility Base 3.5L

VIN: 1FMHK7B84BGA40077

Inv#: 3221

